

K-METRON QUICK START GUIDE

ROTATIONAL MOULDING THICKNESS GAUGE

1. Download the K-METRON USER GUIDE from:
<http://www.493k.com/product-documentation/>
2. Download and install the K-METRON software from:
<http://www.493k.com/software/>
3. With a PC connected to the internet, plug in the receiver unit to a local USB port and allow the devices communication drivers to install.
4. Once installed ensure that the K-METRON software is looking at the correct communication port that Windows has allocated to the K-METRON Receiver (found in Device Manager) – *this must be done manually in K-METRON's Tools/Options menu..*
5. Turn on the handheld K-METRON by momentarily press the ON/OFF switch.
6. Your unit is factory calibrated and the default magnet is the 10mm CUBE (see the user guide on how to change magnet type).
7. Set the sensor head on the item to be measured and couple the 10mm CUBE magnet on the other side of the item in line with the sensor head.
8. The thickness reading will be displayed on the handheld screen.
9. Pulling the orange trigger will transmit the data to the receiver and into the K-METRON software.

