

K-METRON QUICK START GUIDE

493K THICKNESS/COMPARATOR GAUGE

Contact 493k: office@493k.com or +44 28 93359922

1. Download and install the K-METRON USER GUIDE from the link supplied by 493K. If you do not have this link please contact office@493k.com.
2. To turn on the unit momentarily press the ON/OFF switch.
3. Use the factory calibrated 10mm CUBE magnet to measure the thickness.
4. The reading will be displayed on the handheld screen.
5. Download and install the K-METRON software from the link supplied by 493K. If you do not have this link please contact office@493k.com.
6. With PC connected to the internet plug in the receiver unit and allow the communication drivers to install.
7. Ensure the K-METRON software is looking at the correct communication port that Windows has allocated to the Receiver (found in Device Manager).
8. Pulling the orange trigger will transmit the data to the receiver and into the K-METRON software.

